



100% Reliability



Efficient



Oil-free



Reusable



Application Report

Industry	Manufacturing/textiles
Type of Application	Shipment of weaving machines
Project Details	Shipment via sea-freight for approximately 4-6 weeks to Turkey. Further 2-8 weeks shipment and storage within Turkey.
Previous Problems	VCI packaging wrapping over metal components, then packed in wood crate. Extensive corrosion seen throughout shipments. Corroded metal edges, severe rust staining on rear housings. Also consistent ingress of water throughout resulting in serious mould + mildew issues.
Revised Packaging Solution	Machinery wrapped with 6 mil Static Intercept then loaded into crates with desiccant packs.
Benefits and Improvement	Elimination of corrosion issues following initial 6 month program. Customer reports 54% savings of packaging costs.

Application Photos

